






MAP SCALE 1:1250 CREATED DATE: 25/10/2023 PHOTOGRAPHIC COPY LIABLE TO DISTORTION IN SCALE








A1672-24

P2







East Elevation as proposed Scale 1:100



North Elevation as proposed Scale 1:100





AJO

A1672-13

CLS

P1

ПО-МОТ ИДИЛЕТНИЕ СЕВИМОЕ, ТНЕ ОДИТИМЕДТИ В ОЗМИСТ ТО-МИКЕ ОРЕСТИСЕ. А LEMENSHIPM, ОН ИТЕЛЬНО ТАКИ ОДИТИМЕ ОДИ



































MAP SCALE 1:1250 CREATED DATE: 25/10/2023 PHOTOGRAPHIC COPY LIABLE TO DISTORTION IN SCALE








MAP SCALE 1:1250 CREATED DATE: 24/10/2023 PHOTOGRAPHIC COPY LIABLE TO DISTORTION IN SCALE












































































MAP SCALE 1:1250 CREATED DATE: 24/10/2023 PHOTOGRAPHIC COPY LIABLE TO DISTORTION IN SCALE







Projecting brick course immediately beneath rendered capping reinstated after rebuilding of wall. Half-round brick coping with rendered finish reinstated after rebuilding of wall. Level corrected to avoid clash with pillar capping. Existing stone cap to be reinstated centrally on pier, fully bedded and Brick boundary wall to be dismanfied down to sound section (estimated here) and to be nebult essetily to match essisting prior to damage. Ion straps to be carefully removed. Newly rebuilt wall and pillar to be fully bonder.

> North elevation of north pillar and abutting wall Scale 1:20

General notes:

Continue.

The existing bolds gate plan to the north of the coultivary love Lave opening, suffered impact determined in 2023 when solds they available. The three plans passed on the leves time of the plans plans, which is the plans of the plans plans, and an arrival and partial vertically. Through the line of the hisper plans, and an arrival plans plans, and a plans of the plans plans, and the plans plans

Beyond this immediately north of the pillar there are a number of son stages set within the bed-pirts of the britishway of son stages set within the bed-pirts so the britishway on the pillar that the pillar than the pillar

Materials
The waiting and paller pereceity appear to be constructed of a traditional red both, with line motion (though some COZ central based reporting) person course. Despread to the same of the period p

The damage is to be addressed by undertaking the following

- (S) Careful removal of the stone pillar cap. Careful removal of the rendered half-round brick capping and projecting brick course to the abutting boundary wall back to the line of where the batter commences. Careful removal of the stone hinge blocks and steel hinge
- Careful removal of the stone hinge blocks and steel hinge plate.
 Careful disementing of the brick pillar and the abutting boundary wall to the the point at which the remaining brickwork is sound and plumb (estimated to be the levels indicated (shaded section)).
 Careful removal and disposal of the 3 corroded iron

- indicated (whoded accident).

 Careful immoval and disposal of the 3 corrected iron Careful immoval and disposal of the 3 corrected iron Careful immoval and disposal of the 10 cetalistic interest in the 10 cetalistic interest interest in the 10 cetalistic interest interest





South Holland District Council

Ayscoughfee Hall Museum & Gardens Church Gate, Spalding, PE11 2RA

Proposed rebuild of damaged gate pillar (north pillar of east gates - Love

Plans and elevations as proposed

Sept 2023 as shown @ A1 aio

LBC APPLICATION ISSUE

A1572-61 P1

